

HD7100 RS232 Command

OSD Func	Example
OSD	Layout
Power On	Power ON == PON
Power Off	Power Off == CLOFF00
Mode ID	Mode ID== CLMID00
Input Signals-Write	S-Video== CLSIG00
	Composite == CLSIG01
	Component 1 == CLSIG02 orSIG03
	Component 2 == CLSIG04 orSIG05
	DVI == CLSIG06
	PC == CLSIG07
Aspect Ratio-Write	Pixel To Pixel == CLASP00
	Anamorphic == CLASP03
	Letterbox== CLASP09
	Standard == CLASP0B
Aspect Ratio-Read	CLASP??
White Enhance-Write	0-ON
	1-OFF
White Enhance-Read	CLWEN??
ECO. Mode-Write	0-ON
	1-OFF
ECO. Mod-Read	CLECM??

Baud Rate = 9600